




1









M05



1









M04




1




M04









- | | | | |
|----|----|-------|----|
| 1 | 1A | 1B | 1C |
| 2 | 2A | 2B | |
| 3 | | ø8x36 | |
| 4 | | M8x98 | |
| 5 | | | |
| 6 | | | |
| 7 | | | |
| 8 | | | |
| 9 | | | |
| 10 | | | |

 OGI V

A



B



KOLENIŠĆ MONTAŽU
MIMOSPODOV.
THE FITTINGS SEQUENCE OF THE
CAMS.
DIE MONTAGEABFOLGE VON
EXZENTERN.

- | | | | | |
|---|---|---|---|---|
| 1 | 2 | 3 | 4 | 5 |
|---|---|---|---|---|