
















E40






1	 M8x45	2	 M6x16	3	 M6x14	4		NE50_2  x4  x4  x8  x4	NE67  x2  x2  x4  x2	NE67_2  x4  x4  x8  x4	 	BR
---	---	---	---	---	--	---	---	---	---	---	---	-----------




1

M6x14



PL41 - x12
PL42 - x12
PL43 - x12

2




PL41 - x2
PL42 - x2
PL43 - x2

PL..


A

PL41




A

PL42




A


PL43



B



B



B

