

1



M05



1



M04





1





M04














Ⓘ




Ⓣ








Ⓛ



Ⓒ






1		x6
2		x4
3		x4
4		x4
5		x4
6		x4
7		x4
8		x4


Q16_Q19

KOLEJNOŚĆ MONTAŻU
 IMOSRODOW.
 THE FITTINGS SEQUENCE OF THE
 CAMS.
 DIE MONTAGEABFOLGE VON
 EXZENTERN.


①




②




③




④






⑤






Ⓑ




Ⓐ



- | | |
|---|--|
| 1 | |
| 2 | |
| 3 | |
| 4 | |





Q10





1	1A	1B	1C	x6
2				x2
3		ø8x36		x4
4		M6x98		x2
5				x2
6				x2
7				x2
8		M6x14		x12

(A)




(B)




KOLEIŃOŚĆ MONTAŻU
MINOSRODOW.
THE FITTINGS SEQUENCE OF THE
CAMS.
DIE MONTAGEABFOLGE VON
EXZENTERN.


①




②



③



④



⑤

