

1



M05



1



M04



1




M04




- | | |
|----|--|
| 1 | |
| 2 | |
| 3 | |
| 4 | |
| 5 | |
| 6 | |
| 7 | |
| 8 | |
| 9 | |
| 10 | |
| 11 | |





A





KOLENOŠĆ MONTAŻU
MINIŠRODOW.
THE FITTING SEQUENCE OF THE
CAMS.
DIE MONTAGEABFOLGE VON
EXZENTERN.














Ⓘ




Ⓣ








Ⓛ



ⓐ






1		x6
2		x4
3		x4
4		x4
5		x4
6		x4
7		x4
8		x4


Q16_Q19

KOLEJNOŚĆ MONTAŻU
 IMOSRODOW.
 THE FITTINGS SEQUENCE OF THE
 CAMS.
 DIE MONTAGEABFOLGE VON
 EXZENTERN.


①




②




③




④






⑤









Ⓑ







Ⓐ




- | | |
|---|---|
| 1 |  |
| 2 |  $\varnothing 8 \times 36$ |
| 3 |  $\varnothing 7 \times 70$ |
| 4 |  M6X50 |




Q10

1		1A 1B	x6
2			x2
3		ø8x36	x4
4		M6x98	x2
5			x2
6			x2
7			x2
8		M6x14	x12

(A)




(B)




KOLEIŃOŚĆ MONTAŻU
MINOSRODOW.
THE FITTINGS SEQUENCE OF THE
CAMS.
DIE MONTAGEABFOLGE VON
EXZENTERN.


①




②



③



④



⑤

