


|       |       |       |       |       |       |       |       |       |        |  |
|-------|-------|-------|-------|-------|-------|-------|-------|-------|--------|--|
| 1<br> | 2<br> | 3<br> | 4<br> | 5<br> | 6<br> | 7<br> | 8<br> | 9<br> | 10<br> |  |
|-------|-------|-------|-------|-------|-------|-------|-------|-------|--------|--|

KOLEJNOŚĆ MONTAŻU  
MIMOŚRÓDŲ.


THE FITTINGS SEQUENCE OF THE  
CAMs.

DIE MONTAGEABFOLGE VON  
EXZENTERN.




|       |       |       |       |       |  |
|-------|-------|-------|-------|-------|--|
| ①<br> | ②<br> | ③<br> | ④<br> | ⑤<br> |  |
|-------|-------|-------|-------|-------|--|


B







C





D














1

 $\varnothing 5 \times 17$ 

NL41



1

 $\varnothing 5 \times 17$ 

NL41

