




A





B




x4

C



x16





x4



D



E



x2

F

Należy zachować zalecaną kolejność podłączania przewodów.

1. Kabel zasilający
2. Panel sterujący
3. Kable od kolumn

Keep the recommended wiring sequence


1. Power cable
2. Control panel
3. Column cable

Beachten Sie bitte, dass die Leitung in bestimmter Reihenfolge verbunden werden soll.


1. Versorgungsleitung
2. Steuerungspaneel
3. Kabel von Säulen


Veuillez maintenir l'ordre de branchement des câbles.

1. Câble d'alimentation
2. Panneau de commande
3. Câble de la colonne



G






W razie niebezpieczeństwa wyłączyć zasilanie.

In case of danger turn off the power.

Im Gefahrfall die Energieversorgung ausschalten.

En cas de danger, débrancher l'alimentation.



PL:

Należy zachować odstęp co najmniej 25mm pomiędzy blatami biurk

EN:



It is required to maintain at least 25mm distance between the desk's worktops.

DE:


Es soll ein Abstand von mindestens 25 mm zwischen den Tischplatten eingehalten werden

FR:

Une distance minimale de 25 mm est nécessaire entre les plans de travail des bureaux.



J



MAX 200 KG