



- | | | |
|---|--|-----|
| 1 | | x26 |
| 2 | | x23 |
| 3 | | x12 |
| 4 | | x8 |
| 6 | | x6 |
| 7 | | x1 |






MIT8

A



KOLEJNOŚĆ MONTAŻU
MIMOSRODOW I KOLKOW.
THE FITTINGS SEQUENCE OF THE
CAMS AND DOWELS.
DIE MONTAGEFOLGE VON
EXZENTERN UND DÜBELN.





1	 $\varnothing 3,5 \times 16$ x1
2	 x1
3	 $\varnothing 3 \times 16$ x2
4	 $\varnothing 3 \times 16$ x2
5	 5a 5b x1
6	 $\varnothing 3 \times 16$ x2

